
Nissan 350z Engine Timing Chain Marks

*Nissan 350z
Engine
Timing Chain
Marks*

*Downloaded
from
app.ardentx.com
by Travis &
Carney*

UNDERSTANDING THE NISSAN 350Z ENGINE TIMING CHAIN MARKS

The Nissan 350Z, with its iconic VQ35DE and later VQ35HR engines, remains a favorite among sports car enthusiasts and DIY mechanics. One of the most critical maintenance tasks for these engines involves the timing chain system. Incorrect timing chain alignment can lead to poor performance, rough

idling, or even catastrophic engine damage. This comprehensive guide will walk you through everything you need to know about Nissan 350Z engine timing chain marks, from identifying them to correctly aligning them during a repair or replacement.

WHAT ARE TIMING CHAIN MARKS AND WHY DO THEY MATTER?

Timing chain marks are factory-painted or machined indicators on the crankshaft sprocket, camshaft sprockets, and timing

chain links. They ensure that the camshafts and crankshaft rotate in perfect

synchronization, which is essential for proper valve timing. On a Nissan 350Z, using the correct timing chain marks is the only reliable way to avoid valve-to-piston contact and maintain engine efficiency. Even a single tooth misalignment can cause misfires, reduced power, or increased fuel consumption.

The Role of the Timing

Chain in VQ35 Engines

The VQ35DE (produced from 2003 to 2006) and VQ35HR (2007 and later) are both DOHC (dual overhead camshaft) V6 engines. They use a single timing chain that drives both camshaft banks. The chain is tensioned by a hydraulic tensioner and guided by plastic rails. Unlike a belt, the chain itself does not have a scheduled replacement interval, but **tensioner failure or chain stretch** can still occur, especially in higher-mileage engines. When servicing the timing system, you must align the Nissan 350Z engine timing chain

marks precisely to maintain the engine's firing order and valve events.

LOCATING THE TIMING CHAIN MARKS ON A NISSAN 350Z

Before you begin any timing work, you need to know where to find the marks. On all VQ35 variants, there are three primary sets of marks:

- **Crankshaft sprocket mark**
– a notch or dot aligned with a reference point on the oil pump housing or engine block.
- **Left (driver side) camshaft sprocket marks**
– typically a single dot or line on the sprocket that must align

with a notch on the cam cap or cylinder head.

- **Right (passenger side) camshaft sprocket marks**
– similar marks, often color-coded or shaped differently (e.g., a circle vs. a triangle) to avoid confusion.
- **Chain link marks** – the chain itself has colored links (usually blue, yellow, or gold) that correspond to specific sprocket positions.

On the VQ35DE, the timing chain marks are typically painted yellow for the crankshaft and both camshafts. However, aftermarket chains may have different coloring.

Always verify using the factory service manual for your specific model year.

Common Mistake: Confusing Left and Right Bank Marks

One of the most frequent errors when working with Nissan 350Z engine timing chain marks is mixing up the driver and passenger side camshaft marks. The left bank (cylinder 1-3) uses a single dot, while the right bank (cylinder

4-6) uses a double dot or a line. If you swap these, the engine will run with incorrect cam timing, causing rough operation and potential mechanical damage.

STEP-BY-STEP GUIDE TO ALIGNING NISSAN 350Z TIMING CHAIN MARKS

Below is a general procedure for setting the timing chain marks on a VQ35DE engine. Always refer to a factory service manual for torque specifications and special tools. The steps are similar for the VQ35HR, but the tensioner design differs slightly.

Step 1:

Prepare the Engine

Remove the front engine covers, accessory belts, and crankshaft pulley (harmonic balancer). Rotate the crankshaft by hand (using a socket on the crank bolt) until cylinder #1 is at top dead center (TDC) on the compression stroke. You can verify TDC by feeling compression at the spark plug hole or by using a TDC timing tool. At this point, the crankshaft keyway should be pointing upward (approximately 12 o'clock).

Step 2: Check the Cranksha ft Sprocket Mark

On the crankshaft sprocket, you will see a small notch or dot. This mark must align with the pointer on the oil pump housing. If you don't have a clear view, use a mirror or remove the lower timing cover. The **Nissan 350Z engine timing chain marks** for the crank are typically a single yellow painted dot on

the sprocket tooth that aligns with a notch on the oil pump.

Step 3: Position the Camshaft Sprockets

With the crank at TDC, both camshaft sprockets should have their marks pointing upward and inward toward each other. On the left bank, the single dot should align with the notch on the cam cap. On the right bank, the double dots (or a line) should align with the corresponding notch. The sprockets should be free to rotate slightly; if they are not, you may need to

loosen the camshaft sprocket bolts (note: this is only necessary if replacing the chain).

Step 4: Install the Timing Chain

Lay the timing chain over the crankshaft sprocket first, ensuring that the colored link (usually yellow or blue) aligns with the mark on the crank sprocket. Then loop the chain over the left camshaft sprocket, aligning its colored link with the sprocket mark. Finally, route the chain over the right camshaft sprocket, matching its colored link. Some chains have three colored links: one for

the crank, one for the left cam, and one for the right cam. Ensure all links are seated snugly.

Step 5: Install the Tensioner and Guides

Install the chain guides and the hydraulic tensioner. **Do not force the tensioner pin out prematurely.** Once the tensioner is bolted in place, pull the pin to allow the tensioner to take up slack. Never rotate the crankshaft or camshafts after the tensioner is released without verifying all marks again.

Step 6: Rotate and Verify

After assembling, rotate the crankshaft two full turns clockwise (using the crank bolt) by hand. Return cylinder #1 to TDC and recheck all timing marks. The colored links should still align with the sprocket marks. If they do not, you have a timing error and must disassemble and correct it. This verification step is essential and prevents costly mistakes.

COMMON ISSUES AND SOLUTIONS WHEN USING

TIMING CHAIN

MARKS

Even experienced mechanics can encounter problems. Here are the most common issues and how to resolve them:

Misaligned Aftermarket Chains

Aftermarket timing chains sometimes have different colored links or no marks at all. In such cases, you can count the number of links between sprockets. The factory service manual specifies exact link

counts between the crank and each cam sprocket (e.g., 44 links from crank to left cam, 48 from crank to right cam). Use this method as a secondary check. Always prefer OEM chains when accuracy is critical.

Stretched and Worn Marks

On high-mileage engines, the timing chain can stretch enough to cause the marks to appear misaligned even when installed correctly. If you find that you cannot get the marks to line up perfectly even after following the procedure,

ESSENTIAL TOOLS

A new chain should have minimal slack; excessive play indicates stretch and requires a new chain, tensioner, and guides.

Camshaft Sprocket Movement

During installation, camshaft sprockets can shift slightly due to valve spring pressure. Always use a sprocket holding tool (such as the OEM Nissan tool) to prevent rotation. If the sprocket moves, you will lose the correct timing mark alignment and must restart the alignment process.

FOR TIMING CHAIN WORK ON A NISSAN 350Z

To accurately align the Nissan 350Z engine timing chain marks, you will need a few specialized tools in addition to standard sockets and wrenches:

- **Crankshaft pulley puller** – to remove the harmonic balancer without damage.
- **Camshaft sprocket holder** – to prevent rotation when loosening or tightening sprocket bolts.
- **TDC timing tool** (optional but recommended) – to positively locate cylinder #1 top dead center.

- **Torque wrench**
– for critical fasteners like cam sprocket bolts and tensioner bolts.
- **Factory service manual** – the definitive source for your specific year and engine code.

Using the correct tools not only makes the job easier but also ensures that you can trust the **Nissan 350Z engine timing chain marks** you are aligning.

EXPERT TIPS FOR PERFECT TIMING CHAIN ALIGNMENT

Here are additional insights from seasoned Nissan technicians:

- **Mark the chain before removal.** If you are only replacing the

tensioner or guides and the chain appears in good condition, use a paint marker to transfer the relationship between the existing chain and sprockets. This can save time if the factory marks are hard to see.

- **Check valve clearance after timing work.**

On some VQ35 variants, especially after a chain replacement, the valve timing can shift slightly due to cam phasers (if equipped).

Always perform a compression test or leak-down test after reassembly.

- **Prime the oil**

NISSAN 350Z

After reassembling the front of the engine, crank the engine with the fuel pump fuse removed to build oil pressure before starting. This prevents dry start wear on the chain guides and tensioner.

- **Use threadlocker on cam sprocket bolts.** Many 350Z engines have suffered loose cam sprocket bolts due to vibration. Apply medium-strength threadlocker to the bolts and torque to factory specifications.

CONCLUSION: MASTERING THE

TIMING CHAIN MARKS

Accurately setting the Nissan 350Z engine timing chain marks is one of the most technically demanding jobs a home mechanic can undertake, but it is entirely achievable with patience, the correct tools, and a thorough understanding of the engine's design. The key takeaway is to never rely on memory alone—always double-check the marks after rotating the engine, and always consult the factory specifications for your particular model year. Whether you are replacing a worn chain, installing a new tensioner, or simply verifying timing after an engine rebuild, getting these marks

right ensures that your 350Z runs smoothly, efficiently, and reliably for thousands of miles to come. Remember: a misaligned chain can turn a rewarding DIY project into an expensive engine repair, so take your time, follow each step carefully, and let the marks guide you to success.