
Manufacturing Process For Design Professionals

*Manufacturing Process
For Design
Professionals*

*Downloaded from
app.ardentx.com by
Dominik & Sawyer*

BRIDGING THE GAP: UNDERSTANDING THE MANUFACTURING PROCESS FOR DESIGN PROFESSIONALS

For many design professionals, the journey from a brilliant concept to a tangible, market-ready product can feel like navigating a labyrinth. You have meticulously crafted the perfect digital

model, considered ergonomics, and refined the aesthetic until it is flawless on screen. Yet, the moment of truth arrives when that design must meet the physical world. This is where a deep, working knowledge of the manufacturing process becomes not just an advantage, but a necessity. Understanding how your designs will be made—the constraints, the opportunities, and the inherent logic of production—is what separates a beautiful rendering from a successful,

profitable product. This guide is designed to demystify that journey, providing a comprehensive overview of the manufacturing process for design professionals who are ready to see their work come to life.

THE CRITICAL MINDSET: DESIGN FOR MANUFACTURING (DFM)

Before we dive into specific processes, it is essential to adopt the core philosophy that underpins all successful production: Design for Manufacturing, or DFM. This is not a single step but a continuous mindset that should inform every decision you make, from the initial sketch to the final CAD file. DFM is the practice of designing a product so that it is easy and cost-effective to manufacture without sacrificing quality

or function. For design professionals, embracing DFM means proactively communicating with engineers and fabricators, understanding the tolerances of different machines, and making material choices that align with production realities. Ignoring DFM often leads to costly redesigns, delayed timelines, and products that are unnecessarily expensive to produce. By learning the language of the factory floor, you empower yourself to create designs that are both innovative and manufacturable.

Key Principles of

DFM

Adopting a DFM approach involves several core principles that every design professional should internalize. These include:

- **Minimizing Part Count:** A design with fewer parts is generally cheaper to assemble, less prone to failure, and faster to produce. Consider whether multiple components can be combined into a single, more complex part.
- **Standardization:** Using standard, off-the-shelf components like fasteners, bearings, and electronic modules can dramatically reduce costs and lead times compared to designing custom solutions for every element.
- **Simplifying Assembly:** Design components that can only be assembled in the correct orientation (a concept known as "pokayoke" or mistake-proofing). This reduces assembly time, labor costs, and the potential for errors.
- **Optimizing Tolerances:** Specify the loosest tolerances possible that still allow the product to function correctly. Tighter tolerances mean higher costs and slower production. Only use tight tolerances where absolutely critical for fit and function.
- **Choosing the Right Material:** The material you select has a profound impact on the manufacturing process. A material

that is perfect for a 3D-printed prototype may be completely unsuitable, or prohibitively expensive, for injection molding at scale.

THE MAJOR MANUFACTURING PROCESSES: A DESIGNER'S GUIDE

The manufacturing world is vast, but most processes fall into a few fundamental categories. For design professionals, a clear understanding of these categories and their specific characteristics is the key to making informed decisions.

Subtractive Manufacturing: Carving from the Solid

Subtractive processes, as the name implies, begin with a solid block of material and remove unwanted portions to create the final shape. This is the oldest form of manufacturing and remains incredibly relevant today.

CNC Machining is the most common subtractive process for modern design professionals. Computer Numerical Control (CNC) machines—including mills,

lathes, and routers—follow precise digital instructions to cut metal, plastic, and wood. CNC machining offers exceptional accuracy, excellent surface finish, and the ability to create complex geometries. It is ideal for low-to-medium volume production, functional prototypes, and parts requiring high strength and tight tolerances. A key design consideration for CNC is tool access. Your cutting tools are cylindrical, so internal corners will always have a radius equal to the tool's diameter. Designing for sharp internal corners can be impossible or require secondary operations, increasing cost. Similarly, consider the depth-to-width ratio of features to avoid tool deflection and vibration.

Key design questions for CNC: Can

the cutting tools reach all features? Are internal radii appropriate? Are there deep, narrow pockets that could cause tooling issues?

Additive Manufacturing: Building Layer by Layer

Additive manufacturing, commonly known as 3D printing, has revolutionized the approach to prototyping and, increasingly, end-use production. Instead of removing material, it builds objects layer by layer from a digital model. For

design professionals, this offers unprecedented geometric freedom. You can create complex internal lattices, organic shapes, and assemblies with moving parts that are printed in a single build. Fused Deposition Modeling (FDM) and Stereolithography (SLA) are common for prototyping, while Selective Laser Sintering (SLS) and Multi Jet Fusion (MJF) are moving into production-grade parts.

The primary advantage for designers is the elimination of tooling costs. There is no need for expensive molds or dies, making additive manufacturing perfect for customization, complex geometries, and low-volume runs. However, it is often slower than other processes for high-volume production, and surface finish may require post-processing.

Anisotropy is a critical concept here: parts are often weaker in the Z-axis (the build direction) than in the X-Y plane. Orientation of your model on the build plate is a vital design decision.

Key design questions for Additive Manufacturing: Does the design take full advantage of geometric freedom? Is the build orientation optimized for strength and surface finish? Are support structures required, and can they be removed easily?

Formative Manufacturing:

Shaping with Force and Heat

This category covers processes that shape material by applying force, often with heat, using a mold or die. These are typically high-volume, highly repeatable processes where the initial tooling cost is high, but the per-part cost is very low.

Injection Molding is the king of formative processes for plastic parts. Molten plastic is injected under high pressure into a precision-machined steel mold, where it cools and solidifies. It is used for everything from bottle caps to automotive dashboards. For a design professional, injection molding presents a unique set of rules. Uniform wall

thickness is paramount to prevent warping, sink marks, and internal voids. Draft angles (a slight taper on vertical walls) are required to eject the part from the mold. Ribs should be added for strength rather than making walls thicker, and sharp corners should always be avoided to reduce stress concentration and improve material flow.

Other formative processes include **Die Casting** (for metal, similar to injection molding), **Forging** (compressing hot metal), and **Blow Molding** (for hollow plastic parts like bottles). Each has its own design lexicon. For example, in die casting, avoiding thick sections is critical due to porosity concerns, while in forging, the grain flow of the metal can be aligned with the part's stress paths for superior strength.

Key design questions for Formative Manufacturing: Is wall thickness uniform? Are generous radii and draft angles included? Can the part be easily removed from the mold? Is the tooling investment justified by the production volume?

Sheet Metal Fabrication: Cutting and Bending

For many products, from electronics enclosures to architectural elements, sheet metal is the material of choice.

The processes involved are remarkably straightforward but require a specific design sensibility. The sheet is cut (using laser, plasma, or waterjet), then bent (using a press brake) into its final shape.

Designing for sheet metal means understanding the "bend allowance"—the material that stretches or compresses during bending, which must be calculated to achieve the correct final dimensions. The bend radius is also crucial; a bend that is too tight for the material thickness will cause cracking. Holes and features should be placed at a minimum distance from bends to avoid distortion. Flanges, hems, and countersinks are all standard features that add strength and functionality without excessive cost. The process is highly repeatable, cost-

effective for both low and high volumes, and produces robust, lightweight parts.

Key design questions for Sheet

Metal: Is the material thickness consistent with the bend radius? Are holes placed a safe distance from bends? Is the overall part designable from a single sheet (where possible) to minimize waste?

MATERIALS AND THEIR MANUFACTURING AFFINITY

The choice of material is inseparable from the choice of process. A design professional must understand this symbiotic relationship. Here is a brief overview:

- **Thermoplastics (e.g., ABS, Nylon, Polycarbonate):** Highly

versatile. They can be injection molded, 3D printed (FDM, SLS), CNC machined, and thermoformed. Their ability to be repeatedly melted and solidified makes them ideal for recycling and a wide range of forming processes.

- **Thermosets (e.g., Epoxy, Polyurethane):** These materials cure permanently when heated or mixed. They are often used in casting and compression molding. They offer excellent heat and chemical resistance but cannot be remelted. They are common in high-performance composite structures.
- **Metals (e.g., Aluminum, Steel, Titanium):** Metals are typically CNC machined, die cast, forged, or

fabricated from sheet. Additive manufacturing (Direct Metal Laser Sintering) is a rapidly growing option for complex, high-value metal parts. The choice of alloy significantly impacts machinability, strength, and corrosion resistance.

- **Wood and Composites:** Wood is often CNC routed or laser cut. Composites (like carbon fiber) involve laying up sheets of fiber with resin, often in a mold, and curing them. This is a highly skilled, manual process, though automation is increasing.

FROM PROTOTYPE TO PRODUCTION: NAVIGATING THE JOURNEY

For the design professional, the path

from concept to market rarely involves a single manufacturing process. A typical journey might look like this:

1. **Concept Prototyping:** FDM 3D printing is used to quickly iterate on form and ergonomics. Speed and low cost are paramount; material properties are secondary.
2. **Functional Prototyping:** SLA or SLS 3D printing, or CNC machining of a softer metal like aluminum, is used to test fit, function, and basic performance. Parts here must be more robust and accurate.
3. **Bridge Tooling:** Soft tooling (using aluminum instead of hardened steel) might be used for a small run of injection molded parts to test market response or

fulfill initial orders before committing to full production tooling.

4. **Production:** Hardened steel tools are cut for high-volume injection molding. The process is fully automated, and quality control is rigorous. The per-part cost is minimized, and output is maximized.

CONCLUSION: THE ENDURING VALUE OF MANUFACTURING LITERACY

In a world of increasingly complex and interconnected design challenges, the manufacturing process is not a postscript to a design project; it is a

fundamental part of the conversation from the very first idea. For design professionals, fluency in the language of production—from CNC tool paths to injection mold draft angles and additive layer orientation—is a superpower. It allows you to innovate with confidence, communicate effectively with production partners, and ultimately deliver products that are not only beautiful and functional but also viable and profitable. By embracing the principles of DFM and understanding the core processes at your disposal, you transform from a pure stylist into a true creator of tangible, real-world solutions. The gap between the digital and the physical closes when you master the art of making.